

C O R R I G E N D U M

THE EFFECTS OF DUCT SHAPE ON THE NUSSELT NUMBER

M. Emin Erdođan and C. Erdem Imrak
Mathematical & Computational Applications **10**(1), 79-88, 2005.

As was pointed out to us by Mike Yuratich of the TSL Technology Ltd. England, some typographical errors exist. The value of the Nusselt number for a duct of square cross-section should be 3.60795070, correct to eight decimal places. The value of the Nusselt number for a duct of semicircular cross-section should be 4.088019123, correct to nine decimal places. In conclusions, line 6, “it is necessary” should be read “it is not necessary”. The other results of the paper are unchanged.